



<del>167</del> <del>116</del>	GaAs P++	
<del>166</del> <del>115</del>	$\text{Al}_{x1}\text{Ga}_{1-x1}\text{As}$ p	
<del>165</del> <del>114</del>	$\text{Al}_{x2}\text{Ga}_{1-x2}\text{As}$ P+	
<del>164</del> <del>113</del>	$\text{Al}_{x2}\text{Ga}_{1-x2}\text{As}$ und	
<del>163</del> <del>112</del>	$\text{Al}_{x2}\text{Ga}_{1-x2}\text{As}$ N+	
<del>162</del> <del>111</del>	$\text{Al}_{x2}\text{Ga}_{1-x2}\text{As}$ und	
<del>161</del> <del>110</del>	GaAs und	
<del>159</del> <del>108</del>	$\text{In}_{y1}\text{Ga}_{1-y1}\text{As}$ und	} x 1 - 3
<del>160</del> <del>109</del>	GaAs und	
<del>158</del> <del>107</del>	GaAs und	
<del>157</del> <del>106</del>	$\text{Al}_{x2}\text{Ga}_{1-x2}\text{As}$ und	
<del>156</del>	$\text{Al}_{x1}\text{Ga}_{1-x1}\text{As}$ und	
<del>171</del> <del>105</del>	$\text{Al}_{x1}\text{Ga}_{1-x1}\text{As}$ p	
<del>170</del> <del>104</del>	GaAs p+	
<del>151</del> <del>103</del>	AlAs und	} x 2 or 3
<del>152</del> <del>102</del>	GaAs und	
<del>151</del> <del>101</del>	AlAs und	
100	GaAs SI Substrate	

FIG.1








FIG.3